





With 12 GA. Steel Stiffener

Curve Representation

- A = 15 PSF
- B = 20 PSF
- C = 25 PSF
- D = 30 PSF



Curve Representation

- A = 15 PSF
- B = 20 PSF
- C = 25 PSF
- D = 30 PSF